


## Dura Avenue Landfill – Toledo



Pre-remedial photo of Dura Avenue Landfill, on the bank of the Ottawa River, where exposed refuse was draining hazardous chemicals into the river.



Installation of barrier wall along the Ottawa River bank.



Completed barrier wall.



Main body of Dura Avenue Landfill after capping.